Economic Commission for Europe

Inland Transport Committee

Working Party on the Transport of Dangerous Goods

103rd session 07 November 2017 Geneva, 6–10 November 2017

Item 9 of the provisional agenda **Any other business**

Information concerning an event occurred during carriage of dangerous goods according to 1.8.5

Transmitted by the Government of Romania

Occurrence summary

On 10 June 2016 at 9.30 in the morning, during a transport of 840 pieces of empty and defective steel LPG cylinders, an event occurred.

A tractor with a semitrailer that was travelling from a warehouse to a LPG filling centre stopped in the inhabited area of Mihailesti (Buzau county) at km 80 on the national road DN 2/E 85 due to the overheated axle of the semitrailer.

The overheating was due to the seizure of the bearing of the respective wheel.

The overheating caused:

- the explosion of the tyre located on the centre of the triple axle of the semitrailer and
- the fire, which extended to the semitrailer floor and then to the LPG cylinders.

The fire engulfed the vehicles and the cylinders quickly, although the driver acted promptly using the fire extinguishers available on the semitrailer.

The road infrastructure and the electricity network were both affected.

The cause of the accident is clearly the technical problem on the vehicle, no human error having been found.

Proposal

We propose to examine different solutions in order to avoid the repetition of such events taking into account the scientific and technical progress in the field of vehicle equipment.

Some of the technical solutions are regulated at UN level and may be used for certain vehicles in order to avoid the fire or the overheating of axles or brakes.

Annex 1

Report on occurrences during the carriage of dangerous goods in accordance with RID/ADR section 1.8.5

1. Mode								
□ Rail		■ Road						
Wagon number (optional)		Vehicle registration (optional)						
2. Date and location of occurrence								
Year: 2016	Month: JUNE	Day: 10 (Friday)	Time: 09.30 A.M.					
Rail		Road						
□ Station		■ Built-up area						
☐ Shunting/marshalling yard		□ Loading/unloading/transhipment site						
□ Loading/unloading/transhipment site		□ Open road						
Location / Country:		Location / Country: Mihailesti, Buzau county,						
or		on E85 at km 80, Romania						
□ Open line:								
Description of lin	ne:							
Kilometres:								
3. Topography								
□ Gradient/incline								
□ Tunnel								
□ Bridge/Underpass								
□ Crossing								
4. Particular weat	her conditions							
	□ Rain							
□ Snow								
□ Ice								
□ Fog								
□ Thunderstorm								
□ Storm								
Temperature: 22 °C								
5. Description of o								
□ Derailment/Leaving the road								
□ Collision								
□ Overturning/Rolling over								
□ Fire								
■ Explosion								
■ Technical fault								
Additional description of occurrence:								
One of the wheels of the triple axle of the semitrailer was seized causing overheat and the explosion of the tyre. The fire that engulfed the vehicle and the cylinders arose shortly.								
The road infrastructure and the electricity network were both affected								

6. Dangerous goods involved											
UN Number (1)	Class	Packing Group	Estimated quantity of loss of products (kg or <i>l</i>) (2)		Means of containment	Means of containment material	Type of failure of means of containment (4)				
UN 1965, HYDROCARBON GAS MIXTURE, LIQUEFIED, N.O.S.	2	F	-		1	STEEL	3				
(1) For dangerous goods assigned to collective entries to which special provision 274 applies, also the technical name shall be indicated. (2) For Class 7, indicate values according to the criteria in 1.8.5.3.											
(3) Indicate the appropriate number 1 Packaging 2 IBC 3 Large packaging 4 Small container 5 Wagon 6 Vehicle 7 Tank-wagon 8 Tank-vehicle 9 Battery-wagon 10 Battery-vehicle 11 Wagon with demountable tanks 12 Demountable tank 13 Large container 14 Tank-container 15 MEGC			(4) Indicate 1 Loss 2 Fire 3 Explosio 4 Structura		e number						

7. Cause of occurrence (if clearly known)

Technical fault

16 Portable tank

- ☐ Faulty load securing
- ☐ Operational cause (rail operation)
- □ Other:

A tractor with a semitrailer loaded with 840 pieces of LPG cylinders of 11 kg (empty or defective) that moved from the warehouse to the filling centre stopped in the inhabited area of Mihailesti due to the explosion of a tyre (on the triple axle of the semitrailer). The seizure of the bearing of the respective wheel cause overheats. The overheating caused the explosion of the tyre and the fire which extended to the semitrailer floor and then to the cylinders.

8. Consequences of occurrence

Personal injury in connection with the dangerous goods involved:

- □ Deaths (number:)
- □ Injured (number:)

Loss of product:

- Yes
- $\quad \square \quad No$
- ☐ Imminent risk of loss of product

Material/Environmental damage:

- Estimated level of damage ≤ 50,000 Euros
- ☐ Estimated level of damage > 50,000 Euros

Involvement of authorities:

- Yes Evacuation of persons for a duration of at least three hours caused by the dangerous goods involved
 - Closure of public traffic routes for a duration of at least three hours caused by the dangerous goods involved

 \square No

Annex 2

Photos







4