

UNECE
Transport Division
Palais des Nations
CH-1211 Geneve 10
Switzerland


Reykjavik 8. Mars 2013

Ref: 201303-0043/7.01.00

**Report on occurrences during carriage of dangerous goods
in accordance with ADR section 1.8.5**

The Administration for Occupational, Safety and Health in Iceland is the competent authority for classification of substances and for approval of packngs and tanks.

With regards.



Vidir Kristjánsson
Head of The Division of Chemistry and Industrial Hygiene, Explosives and ADR



ECE TRANSPORT DIVISION N° <i>77</i>	
Received on :	13 MAR 2013
Seen by :	
Passed to	<i>H. Kervella</i>
for: Action	<input type="checkbox"/>
Discussion	<input type="checkbox"/>
Information	<input type="checkbox"/>

1. Mode	
<input type="checkbox"/> Rail Wagon number (optional)	<input checked="" type="checkbox"/> Road Vehicle registration (optional)
2. Date and location of occurrence	
Year:2013..... Month: February..... Day:7..... Time: 04:00.....	
<u>Rail</u> <input type="checkbox"/> Station <input type="checkbox"/> Shunting/marshalling yard <input type="checkbox"/> Loading/unloading/transshipment site Location / Country: or <input type="checkbox"/> Open line: Description of line: Kilometres:	<u>Road</u> <input type="checkbox"/> Built-up area <input checked="" type="checkbox"/> Loading/unloading/transshipment site <input type="checkbox"/> Open road Location / Country: .Saudarkrokur/Iceland
3. Topography	
<input type="checkbox"/> Gradient/incline <input type="checkbox"/> Tunnel <input type="checkbox"/> Bridge/Underpass <input type="checkbox"/> Crossing	
4. Particular weather conditions	
<input type="checkbox"/> Rain <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Fog <input type="checkbox"/> Thunderstorm <input type="checkbox"/> Storm Temperature: °C	
5. Description of occurrence	
<input type="checkbox"/> Derailment/Leaving the road <input type="checkbox"/> Collision <input type="checkbox"/> Overturning/Rolling over <input type="checkbox"/> Fire <input type="checkbox"/> Explosion <input type="checkbox"/> Loss <input checked="" type="checkbox"/> Technical fault <input checked="" type="checkbox"/>	
Additional description of occurrence:The tank wall was damaged by corrosion by the charge (hydrochloric acid)Small defect in the rubber coating was observed.The thickness of the botton of the tank was under 1 mmThe charge could leak through the tankbottom.	

