

<b>1. Mode</b>	
<input type="checkbox"/> Rail Wagon number (optional): .....	<input checked="" type="checkbox"/> Road Vehicle registration (optional): .....
<b>2. Date and location of occurrence</b>	
Year: <b>2010</b> ..... Month: <b>November</b> ..... Day: <b>6</b> ..... Time: <b>11:00</b> .....	
Rail: <input type="checkbox"/> Station <input type="checkbox"/> Shunting/marshalling yard <input type="checkbox"/> Loading/unloading/transshipment site Location/Country: ..... or <input type="checkbox"/> Open line: Description of line: ..... Kilometres: .....	Road: <input type="checkbox"/> Built-up area <input checked="" type="checkbox"/> Loading/unloading/transshipment site <input type="checkbox"/> Open road Location/Country: <b>Cologne/Germany</b> .
<b>3. Topography</b>	
<input type="checkbox"/> Gradient/incline <input type="checkbox"/> Tunnel <input type="checkbox"/> Bridge/Underpass <input type="checkbox"/> Crossing	
<b>4. Particular weather conditions</b>	
<input type="checkbox"/> Rain <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Fog <input type="checkbox"/> Thunderstorm <input type="checkbox"/> Storm Temperature: ... °C	
<b>5. Description of occurrence</b>	
<input type="checkbox"/> Derailment/Leaving the road <input type="checkbox"/> Collision <input type="checkbox"/> Overturning/Rolling over <input type="checkbox"/> Fire <input type="checkbox"/> Explosion <input checked="" type="checkbox"/> Loss <input checked="" type="checkbox"/> Technical fault Additional description of occurrence: <p style="text-align: center;"><b>The tank wall was damaged by the charge (hydrochloric acid) due to a defect in the rubber coating. The charge could leak through the insulation of the tank to the outside. It is assumed that the damage to the rubber coating is caused by a flushing nozzle in a cleaning system.</b></p> ..... ..... ..... .....	

