



Humanetics Innovative Solutions, Inc.

Jaw / C4 Contact Issue

Background

It was observed that during dynamic testing the jaw can still get in contact with the C4 accelerometers and cube respectively. This issue has not been brought to our Attention since the modification made to the C4 vertebrae back in Oct. 2001 (moving C4 cube 6mm rearwards)



Proposed Solution

Modify skull and skin in order to have more clearance when the head is rotating forward (similar to ptoposed new head design).

