



**Economic and Social  
Council**

Distr.  
GENERAL

TRANS/WP.29/2002/67/Rev.1/Corr.1  
3 October 2003

ENGLISH ONLY

---

**ECONOMIC COMMISSION FOR EUROPE**

**INLAND TRANSPORT COMMITTEE**

World Forum for Harmonization of Vehicle Regulations (WP.29)  
(One-hundred-and-thirty-first session,  
11-14 November 2003, agenda item 4.3.5.)

PROPOSAL FOR A NEW DRAFT REGULATION:

UNIFORM PROVISIONS CONCERNING THE APPROVAL OF VEHICLES  
WITH REGARD TO THE LOCATION AND IDENTIFICATION OF  
HAND CONTROLS, TELL-TALES AND INDICATORS

Revision 1 – Corrigendum 1

Transmitted by the Working Party on General Safety Provisions (GRSG)



Note: The text reproduced below was adopted by GRSG at its eighty-fourth session, and is transmitted for consideration to WP.29 and AC.1. It is based on documents TRANS/WP.29/2002/67, and informal documents Nos. 8 and 8/Add.1, as amended (TRANS/WP.29/GRSG/63, para. 45).

---

Following paragraph 5.1.2., the paragraphs numbered as paragraphs 5.2.3. (twice), renumber as paragraphs 5.1.3. and 5.1.4.

Table 1, symbol 14, correct to read:

"

14.	Power window lock	 or 	Control	No	
-----	-------------------	--	---------	----	--

"

Footnote 7/, amend to read:

"7/ If a single tell-tale is used to indicate an airbag malfunction, the airbag malfunction symbol (22) must be used."

---