Informal document No. **GRRF-60-18** (60th GRRF, 18-21 September 2006, agenda item 1.2.)

PROPOSAL FOR DRAFT AMENDMENTS TO REGULATION No. 13-H (Braking)

<u>Note</u>: The text reproduced below was prepared by the expert from Germany to insert into the Regulation provisions regarding the periodical technical inspection (PTI) (see report ECE/TRANS/WP.29/GRRF/59, para. 4). The modifications to the current text of the Regulation are marked in **bold** characters.

A. PROPOSAL

Paragraph 5.1.1.5., should be deleted.

Paragraph 5.1.1.6., renumber as paragraph 5.1.1.5.

Add new paragraphs 5.1.4. to 5.1.4.3., to read:

- "5.1.4. Provisions for the periodic technical inspection of braking systems
- 5.1.4.1. It shall be possible to assess the wear condition of the components of the service brake that are subject to wear e.g. friction linings and drums/discs (in the case of drums or discs, wear assessment may not necessarily be carried out at the time of periodic technical inspection). The method by which this may be realized is defined in paragraphs 5.2.11.2. of this Regulation.
- 5.1.4.2. It shall be possible to verify, in a simple way, the correct operational status of those complex electronic systems which have control over braking. If special information is needed, this shall be made freely available.
- 5.1.4.2.1. At the time of type approval, the means implemented to protect against simple unauthorized modification of the operation to the verification means chosen by the manufacturer (e.g. warning signal) shall be confidentially outlined. Alternatively, this protection requirement is fulfilled when a secondary means of checking the correct operational status is available.
- 5.1.4.3. It shall be possible to generate maximum braking forces under static conditions on a rolling road or roller brake tester."

Paragraph 5.2.11.2., amend to read:

"5.2.11.2. Checking the wear of the service brake friction components

<u>Note:</u> This document is distributed to the Experts on Brakes and Running Gear only.

GE.06-

- 5.2.11.2.1. It shall be possible to easily assess eheck this wear on service brake linings from the outside or underside of the vehicle, without the removal of the wheels, by the provision of appropriate inspection holes or by some other means. This may be achieved by utilizing only simple standard workshop tools or common inspection equipment for vehicles. e.g. mirror, endoscope etc. tools or equipment normally supplied with the vehicle, for instance by the provision of appropriate inspection holes or by some other means. Alternatively, acoustic or optical devices fitted to at least one lining per brake per wheel which will warning the driver at his driving position when lining replacement is necessary are acceptable. The yellow warning signal specified in paragraph 5.2.21.1.2. below may be used as the optical warning signal."
- 5.2.11.2.2. Assessment of the wear condition of the friction surfaces of brake discs or drums may only be performed by direct measurement of **the** actual component **or examination of any brake disc or drum wear indicators**, which may necessitate some level of disassembly. Therefore, at the time of type approval, the vehicle manufacturer shall define the following:
 - (a) The method by which wear of the friction surfaces of drums and discs may be assessed, including the level of disassembly required and the tools and process required to achieve this.
 - (b) Information defining the maximum acceptable wear limit at the point at which replacement becomes necessary.

This information shall be made freely available, e.g. vehicle handbook or electronic data record."

Insert new paragraph 12 to read:

"12 TRANSITIONAL PROVISIONS

12.1. Until 24 months after the date of entry into force of the supplement 4 to the original version of this Regulation, Contracting Parties applying this Regulation can continue to grant ECE approvals to the un-amended Regulation."

B. JUSTIFICATION

Following the discussion at the fifty-ninth GRRF session, the expert from Germany prepared this document proposing to insert into Regulation No. 13-H provisions regarding the periodical technical inspection (PTI) (see report ECE/TRANS/WP.29/GRRF/59, para. 4). The existing paragraph 5.1.1.5. is deleted, but the text is re-inserted as new paragraph 5.1.4.3.
