

Transmitted by the expert from Canada

PROPOSAL FOR CORRECTIONS TO REGULATION No. 121
 (Identification of controls, tell-tales and indicators)



Note: The proposed amendments are in bold and strikethrough characters.

A. PROPOSAL

Paragraph 5.2.6., in English, French and Russian versions, amend to read:

"5.2.6. Except as provided in paragraph ~~5.2.9.~~ **5.2.7.**, all identifications of tell-tales, indicators and controls listed in table 1 or ISO 2575:2000 must appear to the driver perceptually upright. In case of rotating control, this paragraph applies to it when such control is in its "off" position. "

Table 1, in French version, amend to read:

42a.	Sous-gonflage (ou y compris défaut de fonctionnement)	 16/	Témoin	Oui	Jaune
42b.	Sous-gonflage (y compris défaut de fonctionnement) avec indication du pneumatique concerné	 16/ 17/	Témoin	Oui	Jaune

B. JUSTIFICATION

Paragraph 5.2.6.: Exemption to requirements set out in this paragraph are listed under 5.2.7. and not in 5.2.9.

Table 1: Item 42a should have the same meaning as English and Russian versions.
