# WorldSID-50M Material Update to GTR IWG





Paul Depinet Mike Beebe March 2, 2011

## Agenda

- ► Necessary Material Changes
  - ATD Materials which become unavailable
  - WorldSID parts requiring change
  - Action plans



#### ATD Materials which become unavailable

- ► Materials are becoming unavailable: Why?
  - Environmental reasons
    - ► Raw materials are banned (EPA, etc...) or undesirable to use
    - ► This will continue to be more common in coming years
    - ► Effects all ATD's
  - Economic Reasons
    - ► Suppliers no longer will supply, change of ownership, no longer profitable for them to produce



## Example of an ATD Materials which has become unavailable from current supplier

#### **►** Examples

- Damping material used on most steel ribs
  - ► SAE committee is working on how to validate new materials
- Ureol
  - ► Plastic used in many dummies
    - ES-1, ES-2, ES-2re
      - Iliac wings, cord holders, shoulders
    - Q dummy family
      - ribs, bones, skull
    - Worldsid-50 & -5
      - Iliac wings, skull



## Other reasons why an ATD Materials may become unavailable

- ► Likely candidates for future problems
  - Lead and lead based ballasts
  - Urethanes
    - ► Mercury catalysts
    - ► Other ingredients
  - PVC vinyl skins
    - ► Phthalates
    - ▶ Metals
- ➤ Over the coming years it is likely some materials will become unavailable



## WorldSID Parts Requiring Change

- ► WorldSID-50
  - Iliac wings
  - Skull
- ► WorldSID-5
  - Iliac wings
  - Skull





# ILIAC WING MATERIAL CHANGE

## Iliac Wing Material Change

#### **▶** Problem

- Ureol material no longer available
- Will run out in coming months

#### ► Action plan

- Design & build new mold
- Develop equivalent material
  - ► Develop process with new material
  - ► Match Ureol at material sample level
  - ► Static & Dynamic component level tests
- Final verifications
  - ▶ Dummy certification tests
  - Dummy pendulum biofidelity tests
  - WorldSID task group trials



## Design & build new mold

► Left side mold complete





## Develop process with new material

► Started trials with thermoset





## Match Ureol at material sample level

► Make material samples for quasi-static and dynamic material sample testing



Quasi-static 3-point bending








Dynamic Impact & Durability Testing

## Static & Component level tests

- **►** Components
  - Ureol iliacs
  - Thermoset iliacs
- ► Stiffness Tests
  - Quasi-static
  - Dynamic drop tower
- Fixture is almost complete







## Final Verification

- **►** Certification Tests
  - Run 5 sets of new iliacs in lab dummy to verify compliance to corridors
- ► Pendulum biofidelity tests
  - Several iliacs
  - 3 velocities
- ▶ Provide several iliacs to WorldSID task group for trials





## 5TH ILIAC MATERIAL CHANGE

## 5<sup>th</sup> Iliac Material Change Plan

- ► Same Ureol blend as 50<sup>th</sup>
- **▶** Plan
  - Complete 50<sup>th</sup> work
  - Use same process and thermoset material blend as for 50<sup>th</sup>
  - Run certification tests with 3 iliac pairs to verify blend
  - Run pendulum biofidelity tests
  - Make parts available to customers to try





## **WORLDSID SKULL**

## Skull

- ► Example of work so far for same replacement on Q & Worldsid dummies
- ► Benchmark material Ureol 100
- ► Candidate replacement: Rencast 6444
- ► Methodology:
  - Resonance
  - Dynamic: Frontal and lateral head drop test
  - Durability: Head drop test
- ▶ Observation in Q10
  - Rencast 6444 appears to have no resonance below 10KHz
  - The part made from Rencast 6444 met cert corridor
  - Barium sulfate was used to ballast the head, need more investigation to compensate weight

