













UN Regulation No. 95

Informal document GRSP-51-13
 (51st GRSP, 21–25 May 2012,
 agenda item 16)

Door locking status at engine running	No auto locking function	Auto locking function	Auto locking function is optional or can be deactivated			
				or		or
Door locking status before impact	unlocked	locked	locked	unlocked	locked non-struck side	unlocked, struck side
						
5.3.1. During the test no door shall open	✓	✓	✓	✓	✓	✓*
5.3.2.1. Possible [...] to open a sufficient number of doors	✓	✓	✓	✓	✓	—*
Demonstration to the Techn. Serv.	Test	Test	Test	In-house data	Test with one vehicle	

1: 30g sled test, closed, unlocked prior test