



Above: Aerial of contaminated lagoons built in flood plain adjacent to River Faughan at Drumahoe. No planning permission, no Environmental Impact Assessment.

Below: Now showing signs of collapse – two places (note bush in middle of lagoon which was growing on side of upper lagoon where the smaller of the land slips took place) (shot 24 August 2017 – River Faughan Anglers).

