

## Haze measurements on PC front windows of German police cars

	number of front window	Type of front window	km driven with front window	delivery date	Installation of front window	Demounting of front window	Haze test results					
							Driver field of vision			Front passenger side		
							Transmission %	min	max	Transmission %	min	max
1	131369	Volkswagen T5	39.123	29.05.09	01.07.09	01.08.11	85,7	1,1	1,4	85,7	0,9	1,3
2	102595	Volkswagen T5	68.903	21.09.07	05.10.07	01.08.11	86,1	0,7	1,1	86,1	0,6	1,2
3	71420	Ford Transit	136.452	07.10.02	16.01.03	13.07.11	87,4	1,3	1,6	87,3	0,9	1
4	156329	MB Sprinter	10.000	11.11.10	03.01.11	03.05.11	85,5	0,6	1,3	85,4	0,6	1,1
5	131377	Volkswagen T5	17.400	29.05.09	17.06.09	08.06.11	85,6	0,4	0,6	85,5	0,3	0,6
6	131387	Volkswagen T5	21.000	11.06.09	18.06.09	08.06.11	86,1	0,3	0,5	86	0,5	0,8
7	146089	MB Sprinter	3.500	19.08.10	17.11.10	27.06.11	84,4	0,5	0,9	84,1	0,5	0,7